

Units that experience a leak in this location will need to have the coil replaced and the redesigned discharge tube installed to prevent future issues. This service letter will allow the standard 4 hour labor allowance for subject units that are beyond the 30 day DOA labor allowance for replacement of the coil and redesigned discharge line, plus refrigerant. Please refer to this Service Letter when submitting a warranty claim for either installation of the Source 1 kit or replacing the coil and discharge line. The redesigned discharge line is available from Source 1 under part number S1-07327984001.

Mark Freund
Sr. Manager, Residential Field Service
Johnson Controls Unitary Products

Jeffrey Nichols
Director of Engineering
Johnson Controls Unitary Products