







NOTES:

1. HORIZONTAL CORD OR PATCH CORD MANAGEMENT TO COMPLETE CAT 5e OR SOLUTION
2. FIRE RETARDENT UL94V-0



Allen Tel Products, Inc.
30 TV5 DRIVE • HENDERSON, NV • 89014

**GB110FK HORIZONTAL CORD
MANAGER WITH LEGS**

