

Brass Hose to Pipe Adapters


MHT = Male Hose Threads MPT = Male Pipe Threads FHT = Female Hose Threads FPT = Female Pipe Threads

Evaporative Cooler Adapter



| PART NUMBER | FPT | MPT | FPT SIDE TAP |
|----------------|------|------|-----------------|
| 7-3098 | 1/2" | 1/2" | 1/8" |
| 7-30912 | 3/4" | 3/4" | 1/8" |


Male Hose - Male Pipe



Tapped 1/2" FPT inside 3/4" MPT.

| PART NUMBER | МНТ | MPT | |
|----------------|------|------|--|
| 2140 | 3/4" | 3/4" | |

Female Swivel




| PART NUMBER | FHT SWIVEL | FPT |
|----------------|---------------|----------|
| 2141 | 3/4" | 1/2" |
| 2142 | 3/4" | 3/4" |
| 2154 | 3/4" | 1/2" MPT |

Female Hose - Female Pipe



| PART NUMBER | FHT | FPT | |
|----------------|------|------|--|
| 2147 | 3/4" | 1/2" | |
| 2148 | 3/4" | 3/4" | |

Female Hose - Male Pipe



Tapped 1/2" FPT inside 3/4" MPT.

| PART NUMBER | FHT | MPT |
|----------------|------|------|
| 2150 | 3/4" | 3/4" |

Male Hose (both ends) - Female Pipe



One end tapped 1/2" FPT.

| PART NUMBER | MHT | FPT |
|----------------|------|------|
| 2151 | 3/4" | 1/2" |

Male Hose - Male Pipe



The 1/2" copper connection is inside the 1/2" MPT.

| PART NUMBER | мнт | МРТ | FEMALE COPPER SWEAT |
|----------------|------|------|---------------------------|
| 2143 | 3/4" | 1/2" | 1/2" |

Female Hose - Male Pipe



The 1/2" copper connection is inside the 1/2" MPT.

| PART NUMBER | FHT | MPT | FEMALE COPPER SWEAT |
|----------------|------|------|---------------------------|
| 2144 | 3/4" | 1/2" | 1/2" |