





These couplings are intended for temporary repair. Do not use on hot water, steam, oxygen, petroleum or similar explosive or combustible mediums.



Brass Compression Couplings

PART NUMBER	CWT	IPS	LENGTH
2916	1/2"	3/8"	2-9/16"
2917	3/4"	1/2"	2-3/4"
2918	1"	3/4"	3"
2919	1-1/4"	1"	3"
2920	1-1/2"	1-1/4"	3-1/4"
2927	--	1-1/2"	3-1/2"



PART NUMBER	CWT	IPS	LENGTH
2921	1/2"	3/8"	5"
2922	3/4"	1/2"	5"
2923	1"	3/4"	5"
2924	1-1/4"	1"	5"
2925	1-1/2"	1-1/4"	5"
2926	2"	--	5"
2929	--	1-1/2"	5"
2930	--	2"	5"



PART NUMBER	CWT	IPS	NPT TEE OUTLET
2935	1/2"	3/8"	1/2"
2936	3/4"	1/2"	3/4"
2937	1"	3/4"	1"
2938	3/4"	1/2"	1/2"
2939	1"	3/4"	1/2"
2940	1"	3/4"	3/4"
2941	1-1/4"	1"	3/4"
2942	1-1/4"	1"	1"
2943	1-1/2"	1-1/4"	1-1/4"
2944	--	1-1/2"	1-1/2"
2946	--	2"	2"

Rubber Washers

Fit Iron Couplings				Fit Brass Couplings					
PART NUMBER	IPS	PART NUMBER		PART NUMBER	CWT	IPS	PART NUMBER	CWT	IPS
2960	3/8"	2965	1-1/2"	2980	1/2"	3/8"	2984	1-1/2"	1-1/4"
2961	1/2"	2966	2"	2981	3/4"	1/2"	2985	2"	—
2962	3/4"			2982	1"	3/4"	2986	—	1-1/2"
2963	1"			2983	1-1/4"	1"	2987	—	2"
2964	1-1/4"								